
PARALLEL CONNECTION OF OHMIC RESISTORS

ELS 2.10

Required kit:
P9901-4D Electricity 1



Material:

Item Code	Qty.	Description
P3310-1S	1	Connecting leads SE, set of 6
P3910-1A	1	Plug-in panel, small
P3910-1B	2	PIB connector
P3910-1C	4	PIB wire, straight
P3910-1E	2	PIB wire, T-shaped
P3910-1G	2	PIB wire, angled
P3910-1J	1	PIB wire, interrupted, with sockets
P3910-2R	1	PIB switch, ON/OFF
P3910-3M	1	PIB resistor 500 Ohm
P3910-3O	1	PIB resistor 1 kOhm

Additionally required:

1	Measuring device
1	Power supply

© Fruhmann GmbH, Austria