
RESISTORS IN PARALLEL AND SERIAL CIRCUITS

ELS 2.11

Required kit:
P9901-4D Electricity 1



Material:

Item Code	Qty.	Description
P3310-1S	1	Connecting leads SE, set of 6
P3910-1A	1	Plug-in panel, small
P3910-1B	2	PIB connector
P3910-1C	3	PIB wire, straight
P3910-1E	2	PIB wire, T-shaped
P3910-1G	2	PIB wire, angled
P3910-1H	2	PIB wire, angled, with socket
P3910-1J	1	PIB wire, interrupted, with sockets
P3910-2R	1	PIB switch, ON/OFF
P3910-3G	1	PIB resistor 100 Ohm
P3910-3M	1	PIB resistor 500 Ohm
P3910-3O	1	PIB resistor 1 kOhm

Additionally required:

2	Measuring devices
1	Power supply

© Fruhmann GmbH, Austria