
DIRECT CURRENT MOTOR

ELS 7.3.1

Required Kits:
P9901-4D SEK Electricity 1
P9902-5P SEK Electromagnetism



Material:

Item Code	Qty.	Description
P2610-2B	1	Spirals for heat radiation, set
P3310-1S	1	Connecting leads SE, set of 6
P3410-2C	1	Magnetic field sensor, SE
P3910-1A	1	Plug-in panel, small
P3910-1B	2	PIB connector
P3910-1C	1	PIB wire, straight
P3910-1G	2	PIB wire, angled
P3910-2R	1	PIB switch, ON/OFF
P3911-1T	1	PIB motor

Additionally required:

	1	Power supply

© Fruhmann GmbH, Austria