
CURRENT INTENSITY IS ALSO TRANSFORMED

ELS 8.11

Required Kits:
P9901-4D SEK Electricity 1
P9902-5P SEK Electromagnetism



Material:

Item Code	Qty.	Description
P3310-1S	1	Connecting leads SE, set of 6
P3320-1I	1	Light bulb, 10 V/50 mA, E10
P3910-1A	1	Plug-in panel, small
P3910-1B	4	PIB connector
P3910-1C	2	PIB wire, straight
P3910-1G	2	PIB wire, angled
P3910-1H	3	PIB wire, angled, with socket
P3910-1J	1	PIB wire, interrupted, with sockets
P3910-2A	1	PIB lamp socket E 10
P3911-1J	1	Iron core laminated, U- and I-core with clamp strap
P3911-2J	1	PIB for coil 800 turns
P3911-2K	1	PIB for coil 2 x 800 turns
P3911-2R	1	Coil 800 turns SE, blue
P3911-2S	1	Coil 2 x 800 turns SE, red

Additionally required:

1	Power supply
2	Measuring devices

© Fruhmann GmbH, Austria