CUT-OUT PEAKS DUE TO SELF-INDUCTION

ELS 8.13

Required Kits:
P9901-4D SEK Electricity 1
P9902-5P SEK Electromagnetism



Material:

Item Code	Qty.	Description
P3310-1S	1	Connecting leads SE, set of 6
P3910-1A	1	Plug-in panel, small
P3910-1B	2	PIB connector
P3910-1C	3	PIB wire, straight
P3910-1E	2	PIB wire, T-shaped
P3910-1G	2	PIB wire, angled
P3910-1H	2	PIB wire, angled, with socket
P3910-2C	1	PIB glow lamp
P3910-2K	1	PIB battery (accu) 1.2V
P3910-2R	1	PIB switch, ON/OFF
P3911-1J	1	Iron core laminated, U- and I-core with clamp strap
P3911-2K	1	PIB for coil 2 x 800 turns
P3911-2S	1	Coil 2 x 800 turns SE, red

Additionally required:

	1	Power supply

© Fruhmann GmbH, Austria