
RESISTANCE AND INDUCTANCE IN AC

ELS 8.16

Required Kits:
P9901-4D SEK Electricity 1
P9902-5P SEK Electromagnetism



Material:

Item Code	Qty.	Description
P3310-1S	1	Connecting leads SE, set of 6
P3310-2E	1	Connecting lead SE, 25 cm, black
P3910-1A	1	Plug-in panel, small
P3910-1B	2	PIB connector
P3910-1D	1	PIB wire, straight, with socket
P3910-1H	2	PIB wire, angled, with socket
P3910-1J	1	PIB wire, interrupted, with sockets
P3910-2R	1	PIB switch, ON/OFF
P3910-3M	1	PIB resistor 500 Ohm
P3911-1J	1	Iron core laminated, U- and I-core with clamp strap
P3911-2J	1	PIB for coil 800 turns
P3911-2R	1	Coil 800 turns SE, blue

Additionally required:

1	Power supply
2	Measuring devices

© Fruhmann GmbH, Austria