
MEASURING THE LUMINOUS INTENSITY

EOS 1.4

Required kits:
P9901-4M Electronics (or P9901-4D Electricity 1 & P9901-4F Electronics supplement)



Material:

Item Code	Qty.	Description
P3310-1S	1	Connecting leads SE, set of 6
P3910-1A	1	Plug-in panel, small
P3910-1B	2	PIB connector
P3910-1C	2	PIB wire, straight
P3910-1D	1	PIB wire, straight, with socket
P3910-1G	1	PIB wire, angled
P3910-1H	1	PIB wire, angled, with socket
P3910-3R	1	PIB resistor 10 kOhm
P3910-4J	1	PIB photo resistor (LDR)

Additionally required:

1	Suitable measuring device
1	Suitable power supply

© Fruhmann GmbH, Austria