
BASE CONNECTION (CURRENT AMPLIFICATION)

EOS 3.3.1

Required kits:
P9901-4M Electronics (or P9901-4D Electricity 1 & P9901-4F Electronics supplement)



Material:

Item Code	Qty.	Description
P3310-1S	1	Connecting leads SE, set of 6
P3910-1A	1	Plug-in panel, small
P3910-1B	3	PIB connector
P3910-1C	3	PIB wire, straight
P3910-1E	1	PIB wire, T-shaped
P3910-1G	2	PIB wire, angled
P3910-1H	4	PIB wire, angled, with socket
P3910-1J	1	PIB wire, interrupted, with sockets
P3910-2K	1	PIB battery (accu) 1.2V
P3910-3M	1	PIB resistor 500 Ohm
P3910-5F	1	PIB potentiometer 470 Ohm
P3910-8A	1	PIB transistor NPN, base left

Additionally required:

2	Suitable measuring device
1	Suitable power supply

© Fruhmann GmbH, Austria